



**FEDERAL ROAD SAFETY CORPS  
NATIONAL HEADQUARTERS,  
CORPS SAFETY ENGINEERING OFFICE  
OLUSEGUN OBASANJO WAY, WUSE ZONE 7**

**VEHICLE INSPECTION AND CERTIFICATION UNIT**

**REPORT OF WEEK 5-11/2025 ON WORLDWIDE VEHICLE RECALLS**

**Date: 24/03/2025**

S/N	VEHICLE MAKE/BRAND	MODEL	PUBLICATION SOURCE & DATE	UNITS AFFECTED	DEFECTS/SAFETY CONCERNS	RISK OF CRASH
1.	Toyota	Sienna Minivan 2020-2025	20/2/2025 United States	168,000	Loose third row seatback bolts. Passenger safety risk in the event of crash.	Major.
		Camry 2018	31/1/2025 United States	858	Incorrectly produced fuel pump may fail without prior warning.	Major
		Corolla, Corolla Cross, Highlander, Tacoma 2023-2024	3/2/2025 North America United States	1700	Faulty design causing airbag not to deploy	Critical
		Camry & Lexus 2024-2025	12/2/2025 United States	41000	Potentially damaged seatbelt	Critical

RESTRICTED

		Tacoma 4WD, Pick-up Trucks. 2024-2025	11/2/2025 Unites States	106,000	Potential brake fluid leaks. Risk of crash	Critical
2.	Acura	MDX 2025, SUV	31/1/2025 United States	9221	Faulty information display unit causing rearview camera image not to display properly	Critical
3.	Kia	EV9, SUV 2025	28/2/2025 United states	Unspecified	Improperly manufactured rear gear drive units that may become damaged due to the motor shaft.	Major
		Seltos, Soul	25/2/2025 United states	137,256	Incorrectly manufactured rings that will lead to engine seized.	Critical
		Niro HEV, PHEV, EV 2023-2024	31/1/2025 United States	80,000	Faulty wiring assembly beneath the front passenger seat causing a condition that prevents the front airbags and seatbelt pretensioners from deploying as intended.	Critical
4.	Subaru	Forster 2025, SUV	31/1/2025 United States	20,300	Incorrectly manufactured vehicle wheels.	Major
5.	Ford	Marverick, Escape. Lincoln corsair hybrid 2024-2025	15/3/2025 United States	Unspecified	Suspect vehicles may shift into neutral unexpectedly, increasing the risk of a crash due to the sudden loss of drive power.	Critical
		Ford Expedition, F-Series pick up 2021-2022	12/3/2025 United states	10,627	Faulty Manufactured brakes may fail.	Critical

RESTRICTED

		Lincoln Navigator SUV 2015-2017	12/3/2025 United states	35,328	Exterior mirror LED lights may cause fire.	Critical
		F-150 Lightning pick-up trucks	9/3/2025 United states	33,510	Battery cell manufacturing defect, could lead to loss of motive power and risk of fire.	Critical
		Mustang Mach E 2020-2022	7/3/2025 United states	Unspecified	High-voltage batteries whose main contactors may overheat in certain scenarios. More specifically, during fast charging on direct current or in case of repeated pedal-to-the-metal acceleration. Risk of fire.	Critical
		Eco Sport SUV 2021-2022	6/3/2025 United states	18,648	Equipped with the 6F15 automatic transmission, both of the front half shafts may disconnect from said tranny, resulting in a loss of drive power.	Critical
		Ford Marverick pick up 2022-2023	5/3/2025 United states	62,813	Incorrectly programmed instrument panel cluster software that prevented the gauges and telltales to illuminate at startup	Major
		Mustang S550 2022-2023	28/2/2025 United states	30,735	Improperly calibrated steering torque sensor that may fail.	Critical
		Bronco 2021-2024	31/1/2025 United States	150,000	Faulty rear shock absorbers that may experience corrosion between the external reservoirs, mounting flanges,	Major

RESTRICTED

					and the damper bodies, leading to a detachment of the reservoirs.	
		Bronco Sport, Escape, Lincoln Corsair. 2025	6/2/2025 United States	Unspecified	Instrument Panel display failure	Major
		Expedition, F-250, F-650. 2021-2022	6/2/2025 United States	72,624	Rear Camera image does not display.	Critical
		Marverick Pick-up Truck. 2021-2023	22/2/2025 United States	1635	Missing Turn signal warning. Could lead to crash.	Critical
		Explorer and Lincoln Aviator SUV,	21/2/2025 United States	240,510	Improperly secured seatbelt buckle anchor bolt.	Critical
6.	Honda	Ridgeline Pick-up 2015-2019	14/2/2025 United states	117,445	Faulty rear view camera image due to wrong wire harness.	Critical
		Pilot, TLX, SUV. 2023-2025	31/1/2025 United States	300,000	Potentially dangerous bug causing software error and engine to stall.	Major
		Pilot SUV 2024-2025	8/2/2025 United states	8849	Improperly routed third-row seatbelt, at the passenger-side assembly.	Major
7,	Mercedes Benz	EQE 350 SUV 2023	13/3/2025 United states	Unspecified	Wheel rim inserts may detach due to manufacture error. Risk of damage to tire and crash.	Critical

RESTRICTED

		AMG Convertible 2023-2025	13/3/2025 United states	3000	A high-voltage starter alternator control unit software deviation may cause sporadic processor overloads, leading to a sudden loss of propulsion.	Major
		S-Class 580 series 2021-2022	28/2/2025 United states	20,339	The front brake hoses of the subject vehicles may fail and leak over time. Reduced braking performance in one circuit obviously increases the risk of a crash, though drivers will notice a red brake fluid warning message in the instrument cluster when sufficient brake fluid exits the system.	Critical
		EQB, SUV, EV 2023-2025	7/2/2025 United states	Unspecified	Potential high voltage battery failure, risk of fire.	Critical
		e-Sprinter Van 2024	23/2/2025 United states	689	Electric Motor failure. Sudden inability to propel of move.	Major
8.	Porsche	Coupe 2023	14/2/2025 United states	911	Improperly tightened buckles and excessive low beam headlights.	Major
9.	Volvo	Volvo S90	26/2/2025 United states	Unspecified	Improperly secured body bonded windows, A condition that can lead to window detachment while driving.	Minor
		EX90 SUV 2025	13/2/2025 United States	2000	A software bug in the lower power controller makes the headlight shutters close over the low and high beams while driving.	Critical

RESTRICTED

10.	Hyundai	GV70, GV80, G80 2023-2025	26/2/2025 United states	36000	Software problems affecting the functionality of the instrument cluster panel. Upon startup, the display is prone to flickering or may become completely inoperative.	Major
		Ioniq 5 N. EV. SUV 2025	13/2/2025 United States	1500	Due to an integrated electronic brake control software problem, depressurization of the anti-lock braking system will occur when using the left-foot braking feature, resulting in reduced braking performance.	Critical
			12/2/2025 United States	Unspecified	Faulty rear side airbags that may not deploy	Critical
11	General Motors	Chevrolet Camaro Cadillac 2024-2025	14/3/2025 United States	90,000	Transmission issue causing momentary lock up of wheels. Risk of crash.	Critical
		Chevrolet Express, GMC Savanah Vans 2025	24/2/2025 United states	94	Door impact beam improperly welded. Increases the risk of injury for driver in the event of crash.	Major
		GMC, Sierra Pick-up trucks. 2022-2023	12/2/2025 Unites States	1500	Detaching Chrome Front Grille Deflectors.	Major
12	Range Rover	Range Rover & Range Rover Sport SUV 2025	15/3/2025 United States	7300	Due to a manufacturing error attributed to a supplier, the rear center seat seatbelt buckle may not latch properly, increasing the risk of injury in the event of a crash.	Critical

## RESTRICTED

		Jaguar Land Rover, Range Rover Evoque SUV, 2020	22/2/2025 United states	1270	Faulty Knee airbag may deploy improperly.	Critical
13	Rivian	R1S and R1T 2025	21/2/2025 United States	2905	Affected vehicles were produced with OP-mobility headlight control modules, which may prevent the low beams from working at startup in cold weather conditions.	Critical
14	Volkswagen	ID.4 & Audi Q4 e-tron 2024	11/3/2025 United states	13,800	Software causing onboard charger to fail. This may lead to either a no-start condition or a sudden loss of motive power and other functions while driving.	Major
		Atlas & Atlas Cross Sport Vehicles 2024-2025	10/3/2025 United states	177,493	Loose engine covers risk of fire.	Critical
		Atlas and Atlas Cross Sport Utility Vehicles(CSUV) 2024.	19/2/2025 United States	Unspecified	Transmission failure.	Critical
		Audi Plug in hybrid A7 and Q5. 2022-2023.	19/2/2025 United States	7221	Faulty batteries that experience thermal overload may lead to a battery fire.	Critical
		Arteon, Tiguan, Audi Q3(Sedan) 2024-2025	19/2/2025 United States	30,000	Rear view camera software issue causing image not to display.	Critical

RESTRICTED

## RESTRICTED

		ID4, Audi Q4 etron SUV, EV 2024.	1/3/2025 United States	60,000	Under specific circumstances, the brake control unit software may prevent the neutral gear position from being displayed in the instrument cluster.	Minor
		MK8 Golf GTI 2021-2024	25/2/2025 United states	15,264	Camera unit software issue. Image does not display.	Critical
15	BMW	X3 30xDrive 2025	26/2/2025 United states	114	Recalled Over Improperly Tightened Electrical Connection, which may result in an engine stall and/or an overheated cable.	Major
		X3, SUV 2024	25/2/2025 United states	41000	Malfunctioning Door Locking Modules, a condition that increases the risk of safety incidents to the rear-seat occupants.	Major
16	INEOS Automotive Group	Grenadier 2024	12/3/2025 United states	7022	Door fails to latch and open unexpectedly. The faulty assemblies were reportedly produced with insufficient grease.	Major

RESTRICTED