



**FEDERAL ROAD SAFETY CORPS  
NATIONAL HEADQUARTERS WUSE ZONE 3, ABUJA  
CORPS SAFETY ENGINEERING OFFICE**

**VEHICLE INSPECTION AND CERTIFICATION UNIT**

**REPORT OF WEEK 47/2024 TO WEEK 4/2025 ON VEHICLE RECALLS**

**Date: 28/01/2025**

S/N	VEHICLE MAKE/BRAND	MODEL	PUBLICATION SOURCE & DATE	UNITS AFFECTED	DEFECTS/SAFETY CONCERNS	RISK OF CRASH
1.	Fisker	SUV, 2024	21/11/2024 United States	7,745	Unintended vehicle movement. The Auto Vehicle Hold (AVH) activates upon depressing the brake pedal while stopped and in drive. Said feature disengages not when the brake pedal is released but rather when the accelerator pedal is depressed.	Critical
2.	Ford	Bronco, Marverick, (2024-2024)	21/11/2024 United States	2400	Electrical system issue caused by incorrect calibrated strategy for detecting sudden battery degradation, results in the inability to restart the vehicle after a stop/start event or the engine stalling at low speeds while coming to a stop.	Major

RESTRICTED

	Expedition, lincon navigator. (2018-2020)	20/11/2024 United States	Unspecified	The seatbelt retractor pretensioner, will deploy without any prior warning.	Major
	Ford Ranger Pick-up 2.7l Ecoboost V6 Engine. 2024	19/11/2024 United States	Unspecified	Insufficient clearance to the fuel vapor line results in a fuel vapor leak.	Critical
	Cross over SUV 2024-2025	20/11/2024 United States	15	Airbag concern. Wrong polyurethane material used in manufacture of airbag.	Critical
	3.5L Ecoboost V6 power truck, SUV, F-150 (2023-2024)	19/11/2024 United States	2418	Engine cup plug leak, resulting in oil leak.	Major
	Explorer 2024-2025.	18/11/2024 United States	27,700	Missing dashboard airbag warning label	Critical
	Marverick, SUV 2023-2024	21/11/2024 United State	465,565	Loss of engine power accompanied by complete electrical system failure.	Major
	B-Max, C-Max, Grand C-Max, EcoSport, Fiesta, Focus, and the Galaxy., 2014-2023	18/12/2024 United States	768,927	Faulty Diesel Particulate Filter (DPF)	Major
	F-150 Truck 2023-2024	24/12/2024 United States	12,000	Faulty front control arm detachment.	Major

RESTRICTED

		SUV plug-in Hybrid Crossover Escape, Lincoln corsair, 2020-2024	3/1/2025 United States	20,484	Battery failure, risk of fire	Critical
		Fiesta, Flex, Lincoln MKT. SUV 2019 .	2/1/2025 United States	30,715	Faulty rear view camera, image becomes distorted, blank, inverted.	Critical
		Lincoln Nautilus 2024-2025	2/1/2025 United States	47,818	Incorrectly calibrated driver and passenger door module software causing power window to pinch	Minor
		F-250, F-750	1/1/2025 United States	300,000	Failing High pressure fuel pumps due to biodiesel deposits	Major
		Maverick pick-up Trick, Bronco sport 2021-2023	23/1/2025 United States	272,817	Battery Failure	Minor
3.	Alfa Romeo	Stelvio, Giulia 2022-2024.	20/11/2024 United States	9037	Incorrect tyre information.	Major
		Giulia sedan, Stelvio Crossover 2019-2020	23/12/2024 United States	1025	Brake pedal detach from booster.	Critical
4.	Polstar	Sedan 2024.	20/11/2024 United States	Unspecified	Brake pedal Detachment.	Critical
		EV (2023-2024)	25/12/2024 United States	2	Improper deployment of airbag	Critical

RESTRICTED

		Model 2S. 2024-2025	6/1/2024 United States	Unspecified	Unexpected loss of drive power due to voltage fluctuations	Critical
5.	Honda	Accord, Accord hybrid (2023-2024)	19/11/2024 United States	121	Improperly tightened Driver's seat frame	Major
		Pilot (SUV) & Passport vehicles 2023-2025.	5/12/2024 United States	200,000	Faulty separation of the fuel filler pipe from the fuel filler neck tube. Risk of fire.	Critical
6.	General Motors	Chevrolet Cutaway 2024.	19/11/2024 United States	75	Missing Rear Vision Camera Video Display	Critical
		Truck & SUVs Chevrolet Silverado, Tahoe, Suburban, GMC, Yukon. Cadillac Escalade, with 3.0 Duramax engine. 2020-2022	16/11/2024 United States	461,839	Faulty rear wheel lock pin	Major
		Chevrolet, GMC Vans. (2022-2023)	15/11/2024 United States	78,000	Incorrect Transmission Control Module (TCM) causing failures in transmission.	Major
		Chevy Silverado HD, GMC Sierra HD Trucks 2023-2024	3/12/2024 United States	6000	Faulty Tailgates Opening While Driving	Major
		Chevrolet Equinox EV, SUV 2025	17/12/2024 United States	7606	Insufficiently Loud Pedestrian Warning Sound.	Major

RESTRICTED

		Chevy Silverdo EV Trucks 2025	3/1/2025 United States	Unspecified	Pedestrian warning sound not loud enough.	Major
		Chevrolet Silverdo EV and Sierra EV Trucks	22/1/2025 United States	Unspecified	Improperly secured rear Centre seat belt	Major
		Chevrolet Equinox EV AWD, SUV 2024-2025	22/1/2025 United States	Unspecified	The brake control module software prevents the adaptive cruise control system from decelerating as intended.	Critical
7.	Lucid Air	Air pure 2024-2025	19/11/2024 United States	1539	Rear sub-frame wiring harness too short, putting a strain on the electrical connection, causing loss of motive power	Major
8.	Range Rover	SUV 2014-2019	18/11/2024 United States	16,759	The front suspension upper knuckle joint of said luxury sport utility vehicles may develop a crack and separate.	Major
		Defender SUV, 2023-2024	11/12/2024 United States	485	Dimensional tolerance mismatch	Major
		SUV ,EV 2022-2023	6/12/2024 United States	12000	Rear View Camera Issue	Critical
		Discovery sport, Defender, Range Rover Evoque. 2023-2024	23/1/2025 United States	28,400	Software bug prompts Rear View Camera Issue	Critical

RESTRICTED

9.	Porsche	Macan Sedan EV 2024-2025	28/11/2024 United States	2941	Incorrect headlight control unit, causing head light to be too bright.	Minor
10.	Maserati	Grecale, Gran-turishmo (2023-2024)	28/11/2024 United States	1710	Rear view camera not displaying due to software malfunction	Critical
11.	Hyundai	Santa Fe, SUV 2024	18/11/2024 United States	Unspecified	Sunshade closes unexpectedly	Minor
		Santa Fe, Elentra sedan 2022-2024	27/11/2024 United States	226,118	Rearview cameras that may fail prematurely due to insufficient solder joints on the printed circuit board.	Critical
		Tucson, Santa Cruz SUV, 2025	23/11/2024 United States	42,465	Vehicle rollaway from improper routed wiring.	Major
		Ioniq-5, EV6 Crossover. 2022-2024	22/11/2024 United States	145,235	Loss of drive power from damaged charging unit	Minor
12.	Mercedes-Benz	Old C-Class, CLK, E-Class, CLS. 2001-2011	26/11/2024 United States	33,456	Detaching glass sunroof panels	Minor
		GLC, S-Class. SUV 2024	16/12/2024 United States	5846	The hex-head screws that secure the rear axle's differential bolt to the carrier may become loose, potentially leading to a separation of the driveshaft from the diff.	Major

RESTRICTED

		Sprinter Van 2018-2022	22/12/2024 United States	Unspecified	The instrument cluster illumination is too bright, not allowing brightness adjustments.	Minor
		E-Class (Sedans & Wagons) 2024	20/12/2024 United States	Unspecified	Faulty Rear axle Carrier	Major
13.	Toyota	Corolla, Corolla Hybrid 2023-2024	26/11/2024 United States	8000	Steering intermediate shaft fracture.	Critical
		RAV4 2024-2025.	10/12/2024 United States	350,331	Loose Brake Caliper and Wheel Hub Bearing Bolts.	Critical
14.	Tesla	EV Model Y 2024	26/11/2024 United States	Unspecified	Improper vehicle welds	Major
		Cybertruck 2024	20/12/2024 United States	694,304	Software Update Issue; tire pressure monitoring system warning light that may turn off between drive cycles	Major
		Model X Crossovers, Model S sedan. 2024-2025	3/1/2025 United States	23,640	Drivers air bag may tear during deployment	Critical
		Model 3, Model S, Model Y and X. 2023-2025	10/1/2025 United States	240,000	Computer board shutting failure	Critical

## RESTRICTED

15.	Volkswagen	ID.4, EV SUV 2023-2024	25/11/2024 United States	400	Peripheral camera control module that prevents the rearview camera image from being displayed on the center touchscreen	Critical
		Atlas 2019	20/12/2024 United States	270	Inadvertent automatic emergency braking.	Critical
16.	Jaguar	SUV 2019	25/11/2024 United States	2760	Safety over Battery fire concerns	Critical
		I-Pace 2019 Saloon	19/12/2024	2760	High voltage battery may overheat and cause fire due to incorrect software update.	Critical
		XE Sedan	26/1/2025 United States	5329	Wiring damage in the trunk, leading to intermittent or no rearview camera image.	Critical
17.	Stellantis Group	Jeep Wrangler 2024	25/11/2024 United States	Unspecified	Wrong dash wiring harness causing inoperative trailer lighting.	Minor
		Grand Cherokee 2024.	18/12/2024 United States	257	Potentially loose radiator cross-member bolts may jeopardize crash sensing and airbag deployment due to compromised intended load distribution or energy management.	Critical

RESTRICTED



RESTRICTED

		Renegade 2021-2023	13/12/2024 United States	2100	Wrong reverse gear lamp configuration and rear bumper backup lamp assembly.	Major
		Jeep Grand Cherokee, Grand Cherokee L, Wagoneer twins 2024	23/12/2024 United States	79,365	Rear view camera image not displaying.	Critical.
		Jeep Cherokee 2023-2024	22/1/2025 United States	63,082	Faulty Power Transfer unit.	Major
18.	Volvo	EX90, SUV, EV 2025	25/11/2024 United States	Unspecified	Improperly tightened second row seat bolt.	Major
		C40 SUV 2024-2025	24/12/2024 United States	Unspecified	Incorrectly produced airbag modules, deploys improperly	Critical
19.	Kia	Ioniq-5, EV6 Crossover. 2024-2025	23/11/2024 United States	62,872	Transient high voltage and thermal cycling, which may damage the integrated charging control unit.	Major
		Sorento PHEV, SUV 2025	17/12/2024 United States	1385	Displaced front frame causes Steering rack to damage fuel line in the event of a crash.	Critical
		EV9 SUV 2024-2025	30/12/2024 United States	23,000	Missing seat mounting bolts	Major
		Sorento SUV.	17/1/2025	74,469	Software error causing headlights to go off unintentionally.	Major

## RESTRICTED

20.	Audi	Q5 PHEV and A7 PHEV 2023-2024	4/12/2024 United States	4616	High-voltage batteries of said plug-in hybrids overheat, potentially leading to more serious thermal events. Risk of fire	Critical
21.	McLaren	765LT Coupe 2024.	4/12/2024 United States	765	Rear windows may detach from the support frame, resulting in a hazard for other road users.	Major
22.	BMW	BMW X4, SUV 2024-2025.	11/12/2024 United States	130	Roof frame crack may damage air bag when deployed	Critical
		BMW X3 SUV, 2025	10/12/2024 United States.	30	Compromised front wheel swivel bearings.	Major
23.	Lexus	NX SUV 2024-2025	10/12/2024 United States	53,515	Loose Brake Caliper and Wheel Hub Bearing Bolts.	Critical
24.	Ram	Heavy Duty Trucks 2023-2024	6/12/2024 United States	402,553	Potential Hydraulic control Unit failure.	Critical
		Trucks 2025	23/12/2024 United States	1500	Inoperative headlights	Critical
		Pick-up Trucks. 2016-2020	24/1/2025 United States	6000	Faulty airbag inflator that may rupture when deployed.	Critical
25.	Vinfast	SUV 2023-2025	25/12/2024 United States	4,888	Incorrect designed airbag that deploys improperly.	Critical
26.	Lamborghini	Revuelto supercar 2024	24/12/2024 United States	Unspecified	Wrong oil circuit connection flange that connects the radiator to the dry-sump oil	Critical

RESTRICTED

RESTRICTED

					tank. Risk of fire.	
27.	Aston Martin	DBX707, DB12 2024-2025	8/1/2025 United States	1452	Obstructed Rear view Camera image.	Critical
28.	Nissan	Crossover SUV 2025	7/1/2025 United States	Unspecified	Unintended movement while in park, the ignition off due to iffy software for the body control module.	Major
29.	Acura	TLX Sedan 2024-2025	6/1/2024 United States	Unspecified	Improperly welded fuel tank and filler neck	Major
		ZDX, SUV EV 2023-2024.	24/1/2025 United States	118	Loose front passenger stabilizer bar bracket bolts, which may detach from the frame. Consequently, the battery cables or battery coolant lines may become damaged.	Major

RESTRICTED

RESTRICTED